

# IMPORTANT CABLING INFORMATION

**RELATING TO: Installation using IEEE 1394/Firewire**

## **WARNING:**

*Please observe correct polarity of the FireWire IEEE1394 connectors at all times. This will mean taking care when making the connection between the cable and the scanner and again when attaching the cable to the FireWire interface on the computer.*

Although the scanner can be 'hot-plugged' to the computer when the scanner and computer are switched on it is not recommended to remove the FireWire connection during scanning as this may require the computer to be restarted to re-establish the software connection.



## **SERVICE & WARRANTY**

If a fault on the scanner can be traced to a failure on the part of the operator to observe the instructions above then any remedial action involving the replacement of electronics by the manufacturer or its agent **WILL NOT BE COVERED** under the terms of the scanner warranty.

PAS122